



City of Tarpon Springs, Florida

BUILDING DEVELOPMENT DEPARTMENT
324 EAST PINE STREET
P.O. BOX 5004
TARPON SPRINGS, FLORIDA 34688-5004
(727) 942-5608

KEVIN POWELL, CBO, CFM
BUILDING DEVELOPMENT DIRECTOR

9/4/2018

Re-inspection Fees

Re-inspection fees, A.K.A. “red tags” are imposed for every inspection that is required due to a previous dis-approved inspection in the same category and trade. Re-inspection fees are not to be considered fines or punishment for any reason. This department does not impose re-inspection fees for the purposes of collecting additional revenues, but solely for re-numeration to cover the additional time, travel, vehicle expense and clerical time associated with the inspection requested.

The building inspector on site has the sole discretion of removing the re-inspection fee based on the jobsite conditions and any extenuating circumstances that may be applicable. Any questions or concerns relating to any re-inspection fees must first be directed to the building inspector that assessed the fees prior to any managerial involvement. Re-inspection fees can only be removed by the building inspector that originally assessed the fees.

The first re-inspection fee will be assessed at \$30.00, the second re-inspection fee for the same category, trade and items that were previously noted will be assessed for \$90.00